

Due to the chemical and corrosion characteristics of aluminium, always comply with the following points when handling aluminium components:

- Do not bring into contact with battery acid!
- Do not clean with wire brushes with brass or iron bristles! Only use brushes with stainless steel bristles!
- Do not expose to flying sparks from grinding/cutting operations! Cover components!
- Do not subject to steel welding splashes! Cover components!
- Do not expose to temperatures > 80° C, even for short periods! Temperatures in painting facilities are not a problem.